



Armature voltage	+	A	1B1	A1	DC motor uncompensated with commutating pole winding
	-	B	2B2	B2, A2	
Excitation voltage	+	I	F1	E1	
	-	K	F2	E2	